

# Mechatronics

## Instructor Required Items



Please note: The items listed are a requirement for this program. Please see your instructor for further details about when the items are needed for your program.

### **First Trimester Required Training: Student Cost \$50.00**

OSHA 10 Class

### **First Trimester Required Supplies:**

Welding Helmet  
Welding Jacket  
#5 shaded Face Shield  
Chipping Hammer

Wire Brush  
Safety Glasses  
Welding Gloves  
Calculator

### **First Trimester Required Tools:**

Wire strippers  
Needle Nose Pliers  
Flat Head Screw Driver

#2 Phillips Head  
#0 Phillips Head  
Precision screwdriver, flat head

### **Third Trimester Required Tools:**

12" Plastic Tool Box  
3/8" Tool Bits HS - qty 4  
Center Drill - qty 2  
Round Edge Finders  
6" Scale English  
8" Adjustable Wrench  
8" Square Nose Side Cutters  
Crimping Tool

Flat Center Gauge  
Center Punch  
Scribe  
Dial Caliper  
0-1 Micrometer  
Fuse Puller  
Tape Measure (25 ft)